

www.connecttech.com

## **Product Change Notification**

## Photon NGX002, NGX003 Rudi-NX ESG602

PCN Number:	CTIU-00032
Revision:	0.00
Issue Date:	2021-03-23
Effective Date:	2021-03-23

### **Connect Tech Inc.**

42 Arrow Road, Guelph, ON CANADA N1K 1S6

Tel: 519.836.1291 • North America: 800.426.8979 • Fax: 519.836.4878

sales@connecttech.com • <a href="http://www.connecttech.com">http://www.connecttech.com</a>

Copyright © 2020 Connect Tech Inc. ALL RIGHTS RESERVED. Connect Tech Confidential: This copyrighted work and all information are the property of Connect Tech Inc., contain trade secrets and may not, in whole or part, be used, duplicated, or disclosed for any purpose without prior written permission of Connect Tech Inc. All Rights Reserved. The Connect Tech Inc. logo is a registered trademark of Connect Tech Inc. All other trademarks used in this document are the property of their respective owners.



### 1 Product Identification

### 1.1 Product Data

	Current Version	Future Versions	
Product Name	Photon Carrier Board	Photon Carrier Board	
CTI Part Numbers	NGX002, NGX003	NGX002, NGX003	
Hardware Revision	E	F	
Product Name	Rudi-NX	Rudi-NX	
CTI Part Numbers	ESG602	ESG602	
Hardware Revision	С	D	

### 1.2 Means of Distinguishing Changed Products

		Remark
<b>Product Number</b>	$\checkmark$	NGX002, NGX003
Hardware Revision	<b>V</b>	E
Lot Code		
Label		
Other		

		Remark
<b>Product Number</b>	$\checkmark$	ESG602
Hardware Revision	<b>V</b>	С
Lot Code		
Label		
Other		



### 2 Description and Reason of Change

AVL	Product Improvement	✓
Material	BIOS Release	
Assembly Process	Firmware Release	
Assembly BOM	Datasheet / Manual	
Testing	DFM	
Manufacturing Site	Other	
Equipment		

#### Photon Carrier Revision E and Rudi-NX Revision C

Due to an internal component being used on Photon Carrier (Revision E) and Rudi-NX (Revision C), there is potential that HDMI shows as plugged in even when it is left unconnected on the Serial Debug UART. This may cause issues in some applications and/or configurations. If you are experiencing this issue please contact <a href="mailto:support@connecttech.com">support@connecttech.com</a> to arrange for RMA and modification.

Note: If HDMI is connected/used in your application this will have no effect on your application or performance.

All NGX002 Photon Carriers with SN: 3136 and later will already have this fix implemented. All NGX003 Photon Carriers with SN: 3336 and later will already have this fix implemented. All Rudi-NX Systems with SN: 1211 and later will already have this fix implemented.

# 3 Impact of change (positive or negative) on fit, form, function & reliability

### 3.1 Quality and Reliability

There are no changes to quality or reliability.

### 3.2 Software Compatibility

There is no change to software compatibility.

### 3.3 Hardware Compatibility

There is no change to hardware compatibility.

### 3.4 Mechanical Compatibility

There is no change to mechanical compatibility.

### 4 Product / Revision Discontinuation

After the release of this document only updated product with this PCN applied will be shipped.

### **5** Contact Information

Phone	+1-519-836-1291
Email	sales@connecttech.com