

# **Product Change Notification**

# Forge/Anvil Startup Performance on Early Revisions

PCN Number:	CTIU-00073	
Revision:	0.00	
<b>Issue Date:</b> 2023-11-27		
Effective Date:	2023-11-27	

### **Connect Tech Inc.**

489 Clair Rd. W., Guelph, ON CANADA N1L 0H7 **Tel:** 519.836.1291 O **North America:** 800.426.8979 O **Fax:** 519.836.4878 sales@connecttech.com O <a href="http://www.connecttech.com">http://www.connecttech.com</a>



## 1 Product Identification


### 1.1 Product Data

	Original Product	
Product Name	Anvil Embedded System	
Part Numbers	ESG620, ESG621 (See table below)	
Product Name	Forge Carrier Board	
Part Numbers	AGX201 (See table below)	

# 1.2 Means of Distinguishing Affected Products

The affected products can be identified by specific serial numbers as shown below

Product	Serial Number
AGX201-###	1830 and lower
ESG620-###	1086 and lower







# 2 Description and Reason of Change

AVL	Product Improvement	$\checkmark$
Material	BIOS Release	
Assembly Process	Firmware Release	
Assembly BOM	Datasheet / Manual	
Testing	DFM	
Manufacturing Site	Other	
Equipment		

Connect Tech has identified certain edge cases and environmental conditions that may affect the startup performance of the Jetson AGX Orin module used on early revision Forge/Anvil products.

This startup performance issue has been ratified in later revisions of the PCBA for the Forge/Anvil products. Earlier revision PCBA's identified by the serial number ranges above can have this issue resolved via an ECN fix applied by Connect Tech Inc.

If you wish to have this ECN applied to your product, please <u>contact support</u> to get an RMA issued to have the ECN fix applied.



# Impact of change (positive or negative) on fit, form, function & reliability

#### 3.1 **Quality and Reliability**

Connect Tech has identified certain edge cases and environmental conditions that may affect the startup performance of the Jetson AGX Orin module used on early revision Forge/Anvil products.

#### **Software Compatibility** 3.2

No impact.

### 3.3 **Hardware Compatibility**

The startup performance issue has been ratified in later revisions of the PCBA for the Forge/Anvil products. Earlier revision PCBA's identified by the serial number ranges above can have this issue resolved via an ECN fix applied by Connect Tech Inc. This issue only effects AGX201-### Serial Numbers 1830 and lower, and ESG620-### Serial Numbers 1086 and lower.

### **Mechanical Compatibility** 3.4

No impact.

# **Product / Revision Discontinuation**

Future orders of the above mentioned products will have the issues fixed and resolved.

### **Contact Information**

Phone	+1-519-836-1291
Email	sales@connecttech.com